



Photo 1: View of wash-out into Kalamazoo River at beginning of removal, facing northeast



Photo 2: View of Kalamazoo River after removing general fill material, facing northeast





Photo 3: First bucket of material removed, facing northeast



Photo 4: View of removal area after first bucket, facing northeast





Photo 5: Turbid condition slightly upstream of removal area, facing east



Photo 6: Another bucket of material removed, facing northeast





Photo 7: View of removal area after additional bucket of material removed, facing northeast



Photo 8: View of upstream location clearing after approximately 4 minutes, facing east





Photo 9: Additional removal of material, facing northeast



Photo 10: Another view of removal of material, facing northeast





Photo 11: View of turbid conditions downstream (~275 feet away from removal area), facing southeast



Photo 12: Close-up of turbid conditions downstream, facing southeast





Photo 13: View of river near removal area approximately 8 minutes after a stop in removal activities, facing southeast



Photo 14: Additional removal of material, facing northeast





Photo 15: View of removal area approximately 9 minutes after a stop in removal activities, facing northeast



Photo 16: View of additional removal of material, facing north





Photo 17: Close-up of removal area after removal of additional material, facing north



Photo 18: Close-up of removal area approximately 14 minutes after removal of material, facing southeast





Photo 18: View of downstream location approximately 16 minutes after stopping removal activities, facing southeast



Photo 19: View of downstream location approximately 16 minutes after stopping removal activities, facing northeast





Photo 20: View of removal area approximately 19 minutes after stopping removal activities, facing southeast



Photo 21: Another view of removal area approximately 19 minutes after stopping removal activities, facing east





Photo 22: Another view of removal area approximately 24 minutes after stopping removal activities, facing northeast



Photo 24: View of downstream location approximately 37 minutes after stopping removal activities, facing southeast

